

General Environmental Incident Summary

Incident: 1957 **Date/Time Notice:** 6/26/2013 0900 **DEM Incident No:**
Responsible Party: Southern Energy Transportation
Date Incident: 6/25/2013 **Time Incident:** 1700 **Duration:** 3 minutes
County: McKenzie **Twp:** 152 **Rng:** 101 **Sec:** 19 **Qtr:** SE NE NW
Lat: 47.97772 **Long:** -103.66330 **Method:** Navigation quality GPS
Location Description: Bridger Transfer Services Crude Oil Storage Facility: Alexander Facility
14361 39th St NW, Alexander, ND 58831

Submitted By: David Lamay **Affiliation:**

Address:

City: **State:** **Zip:**

Received By:

Contact Person: Otis Randle
800 Spring Street, Suite 205
Shreveport, LA 71101

Distance Nearest Occupied Building: 1 Miles

Type of Incident: Pump Leak

Description of Released Contaminant: Hydraulic Fluid

Volume Spilled: 20.00 gallons

Ag Related: No

EPA Extremely Hazardous Substance: No

Reported to NRC: Unknown

Cause of Incident:

Mechanical Failure in pumping system on crude oil trailer

Risk Evaluation:

No immediate risk associated with release

of Fatalities: 0 **# of Injuries:** 0 **Affected Medium:** 03 - soil

Potential Environmental Impacts:

potential soil impact but release contained on the gravel driveway and all contaminated media remediated Tuesday evening.

Action Taken or Planned:

Driver reported directly to load dispatcher and field personnel were dispatched to site for evaluation. Outwest Oilfield Services was called to site to remediate all contaminated media and transport waste to approved disposal site.

Wastes Disposal Location: All waste will be disposed of by Outwest Oilfield Services

Agencies Involved:

Updates

Date: 6/26/2013

Status: Reviewed; Followup Required

Staff: Roberts, Kris

Updated Volume:

Notes:

Release occurred at truck to pipeline transfer facility. Please follow-up to confirm cleanup.

Date: 6/27/2013

Status: Inspected

Staff: Stockdill, Scott

Updated Volume:

Notes:

N 47.977722

W -103.663333

Arrived at location at 1:00 PM on 6/27/2013.

Spill occurred at a transfer station. Hydraulic oil has been cleaned up and no sign of spill remains.
No further action necessary.